


# What can hurt you here?



- 1) Shut off and lock tun heat source
- 2) Close and lock the inlet hot water
- 3) Shut off and lock mash rake
- 4) Shut off and lock grain feed system
- 5) Close and lock re-circulation loop
- 6) Shut off and lock CIP
- 7) Close and lock the outlet out of tun
- 8) Is sparge separate from inlet water
- 9) ?

Tony McCrimmon

[Brewery.safety.consulting@gmail.com](mailto:Brewery.safety.consulting@gmail.com)


Facebook: @brewery.safety.consulting



# Create a Lock Out Tag Out procedure for your equipment



- 1) Shut off and lock tun heat source
- 2) Close and lock the inlet hot water
- 3) Shut off and lock mash rake
- 4) Shut off and lock grain feed system
- 5) Close and lock re-circulation loop
- 6) Shut off and lock CIP
- 7) Close and lock the outlet out of tun
- 8) Is sparge separate from inlet water?



- 1) \_\_\_\_\_
- 2) \_\_\_\_\_
- 3) \_\_\_\_\_
- 4) \_\_\_\_\_
- 5) \_\_\_\_\_
- 6) \_\_\_\_\_
- 7) \_\_\_\_\_
- 8) \_\_\_\_\_
- ?) \_\_\_\_\_
- ?) \_\_\_\_\_